

QA01718 - EMC emissions from charger

Contact details E Tuk Factory B.V.
Verrijn Stuartweg 24 E
1112AX Diemen
Noord-Holland
The Netherlands

Date 10 Sept 2021

List of affected vehicles

VIN	Action
XN7TBA1001M040006	Add extra filter to the Newteq charger
XN7TBA1001M040007	Add extra filter to the Newteq charger
XN7CBA2001L060003	Add extra filter to the Newteq charger
XN7CBA2001L060004	Add extra filter to the Newteq charger
XN7CBA2002J080007	Add extra filter to the Newteq charger
XN7TBA1001L030003	Add extra filter to the Newteq charger
XN7TBA1001L030006	Add extra filter to the Newteq charger
XN7TBA1001L030007	Add extra filter to the Newteq charger
XN7TBA1001L030018	Add extra filter to the Newteq charger
XN7TBA1001L030021	Add extra filter to the Newteq charger
XN7TBA1001L030022	Add extra filter to the Newteq charger
XN7TBA1001L030028	Add extra filter to the Newteq charger
XN7TBA1001L030030	Add extra filter to the Newteq charger
XN7TBA1001L040011	Add extra filter to the Newteq charger
XN7TBA1001L040012	Add extra filter to the Newteq charger
XN7TBA1001L050001	Add extra filter to the Newteq charger
XN7TBA1001M030006	Add extra filter to the Newteq charger
XN7TBA1001M040003	Add extra filter to the Newteq charger
XN7TBA1001L030025	Add extra filter to the Newteq charger
XN7TBA1001M040004	Add extra filter to the Newteq charger

QA01717 - EMC immunity behavior

Contact details E Tuk Factory B.V.
Verrijn Stuartweg 24 E
1112AX Diemen
Noord-Holland
The Netherlands

Date 10 Sept 2021

List of affected vehicles

VIN	Action
XN7TBA1001M040003	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030025	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001M040004	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030004	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040009	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001M040005	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001M040007	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2001L060003	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2001L060004	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J080006	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J080007	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001A070012	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030003	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030006	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030007	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030014	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030015	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030016	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030017	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030018	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030021	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030022	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030023	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030024	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030026	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030027	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030028	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030030	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030032	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040001	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040002	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040003	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040004	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040005	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040006	Install ferrite at BDI, replace optoadapter at speedometer

QA01717 - EMC immunity behavior

Contact details E Tuk Factory B.V.
Verrijn Stuartweg 24 E
1112AX Diemen
Noord-Holland
The Netherlands

Date 10 Sept 2021

List of affected vehicles

VIN	Action
XN7TBA1001L040011	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040012	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001M030006	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002J120005	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002J120006	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K030010	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K040008	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050006	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040007	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040008	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L040010	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L050001	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L050002	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L050003	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L050004	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030001	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030005	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030008	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030009	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030013	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2001L060002	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J120012	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030011	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002J100005	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030012	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J080002	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J080003	Install ferrite at BDI, replace optoadapter at speedometer
XN7CBA2002J080009	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030029	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001M040006	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030010	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030019	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030020	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K040007	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050002	Install ferrite at BDI, replace optoadapter at speedometer

QA01717 - EMC immunity behavior

Contact details E Tuk Factory B.V.
Verrijn Stuartweg 24 E
1112AX Diemen
Noord-Holland
The Netherlands

Date 10 Sept 2021

List of affected vehicles

VIN	Action
XN7TBA1002K050003	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050004	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050007	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050008	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050009	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050010	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1002K050011	Install ferrite at BDI, replace optoadapter at speedometer
XN7TBA1001L030002	Install ferrite at BDI, replace optoadapter at speedometer